


## Container Loading Report

Report Date: May 28, 2011	Booking No.: HIBSS11050067	Report No.: HIBSS11050067	Page 1 of 11
---------------------------	----------------------------	---------------------------	--------------

### A. GENERAL

Client Name:	XXXXXXXX		
PO No.:	0017/1702930 ;0057/5719896		
From:	TSInspection Service		
Contact:	Angie Zhou		
Inspector Name:	Simon Zhao		
Date of Loading:	May 27, 2011		
Time of loading start:	11:00		
Time of loading finish:	16:30		
Loading Location:	TANGSHAN, HEBE	Product Description:	<b>SANITARY WARES</b>
Vendor /Supplier Name:	TANGSHAN XXXXX INDUSTRIAL CO.,LTD	Item/Style/SKU No.:	FP-352700WH-CH FP-352701WH-CH FP-352702WH-CH FP-352703WH-CH FP-352704WH-CH
Factory Name:	TANGSHAN XXXX SANITARY WARES MANUFACTURING CO., LTD		
Destination Country:	UK	Order Quantity:	2432PCS
Country of Origin:	CHINA	Loading Quantity:	2432PCS

Time of start:	5:10	Time of arrival at factory:	10:10
Time of leave factory:	16:40		

### B. INSPECTION RESULT SUMMARY (Refer to following pages for details)

	PASSED	FAILED	PENDING	REMARKS
QUANTITY & ASSORTMENT (Sec D)	X			
CONDITION OF CONTAINER(S) (Sec E)	X			
CONDITION OF EXPORT CARTONS (Sec F)	X			
SHIPPING MARKS (Sec H)	X			
OVERALL RESULT	PASSED		* Refer to Section C for Remarks	

### C. REMARKS

1	N/A
---	-----

## Container Loading Report

Report Date: May 28, 2011	Booking No.: HIBSS11050067	Report No.: HIBSS11050067	Page 2 of 11
---------------------------	----------------------------	---------------------------	--------------

### D. QUANTITY & ASSORTMENT

Item/Style/SKU No.	Product Description	Order Qty (pcs)	Declared Qty of Export Carton (cartons)
FP-352700WH-CH	GEORGIA HO PAN	608	608
FP-352701WH-CH	GEORGIA CC CISTERN	608	608
FP-352702WH-CH	GEORGIA 1TH BASIN	84	84
FP-352703WH-CH	GEORGIA 2TH BASIN	220	220
FP-352704WH-CH	GEORGIA PEDESTAL	608	608
<b>Total:</b>		<b>2432</b>	<b>2432</b>

*Note: TSInspection counts and records the total number of export cartons loaded. By multiplication the inspector calculates the estimated total number of individual products (Calculated Quantity). The inspector does not necessarily examine and/or count every individual product in the shipment.*

### E. CONDITION OF CONTAINER(S)

<b>X</b>	<b>PASSED</b> - Dry and in good working condition, free from stains, bad odors, large dents and holes, suitable for loading the said cargo.
	<b>FAILED</b> - Dirty, with stains, torn roof/side panels, broken hinges/handles or closure devices, etc.
	Other:

### F. CONDITION OF EXPORT CARTONS

<b>X</b>	<b>PASSED</b> - Dry and in good working condition, free from serious damage, suitable for holding and protecting the said cargo, properly palletized.
	<b>FAILED</b> - Crushed, with large holes, containing other serious damage, not suitable for holding and protecting the said cargo, improperly palletized.
	Other:

### G. CONDITION OF LOADING LOCATION

<b>Loading Location:</b>	<b>X</b>	Factory		Warehouse		Other _____	
<b>Weather:</b>		Rainy	X	Sunny		Snowy	Other _____
<b>Sheltered:</b>		Yes	X	No			

 <p>Map</p>	 <p>Factory</p>
--	---

## Container Loading Report

Report Date: May 28, 2011	Booking No.: HIBSS11050067	Report No.: HIBSS11050067	Page 3 of 11
---------------------------	----------------------------	---------------------------	--------------

### H. SHIPPING MARKS

Shipping Marks on	2	Side(s)	Side Marks on	2	Side(s)	Inner Box Marks on	/	Side(s)
Pls see below photo			Pls see below photo			Pls see below photo		

### I. CONTAINER DETAILS

Container Type	Container No.	Seal No.	Loading Time	Loaded Cargo	
				Item / Style No.	Loaded Carton
40H	CMAU4131235	A0590659	11:00-14:00	FP-352700WH-CH	304
				FP-352701WH-CH	304
				FP-352703WH-CH	304
				FP-352704WH-CH	304
40H	FCIU8235315	A0590658	14:20-16:20	FP-352700WH-CH	304
				FP-352701WH-CH	304
				FP-352702WH-CH	84
				FP-352703WH-CH	220
				FP-352704WH-CH	304

### J. ATTACHMENTS

**Photos:**

	
Product in warehouse	Product in warehouse

## Container Loading Report

Report Date: May 28, 2011


Booking No.: HIBSS11050067

Report No.: HIBSS11050067

Page 4 of 11



Master carton



Label stuck on master carton



Product packing



Product



Master carton



Label stuck on master carton



## Container Loading Report

Report Date: May 28, 2011

Booking No.: HIBSS11050067

Report No.: HIBSS11050067

Page 5 of 11




Product packing



Product



Master carton



Label stuck on master carton



Product packing



Product

## Container Loading Report

Report Date: May 28, 2011


Booking No.: HIBSS11050067

Report No.: HIBSS11050067

Page 6 of 11



Master carton



Label stuck on master carton




Product packing



Product



Master carton



Label stuck on master carton



## Container Loading Report

Report Date: May 28, 2011

Booking No.: HIBSS11050067

Report No.: HIBSS11050067

Page 7 of 11



Product packing



Product

First container:



Overall view of container



Container No. outside of container



Container No. inside container



Empty container

## Container Loading Report

Report Date: May 28, 2011	Booking No.: HIBSS11050067	Report No.: HIBSS11050067	Page 8 of 11
---------------------------	----------------------------	---------------------------	--------------



1/4 loading



2/4 loading



3/4 loading



Full loading



Right door closed



Container door closed



## Container Loading Report

Report Date: May 28, 2011

Booking No.: HIBSS11050067

Report No.: HIBSS11050067

Page 9 of 11



Close-up of sealed container



Close-up of seal

Second container:



Overall view of container



Container No. outside of container



Container No. inside container



Empty container

## Container Loading Report

Report Date: May 28, 2011

Booking No.: HIBSS11050067

Report No.: HIBSS11050067

Page 10 of 11



1/4 loaded



2/4 loaded



3/4 loaded



Fully loaded



Right door closed



Container door closed



## Container Loading Report

Report Date: May 28, 2011	Booking No.: HIBSS11050067	Report No.: HIBSS11050067	Page 11 of 11
---------------------------	----------------------------	---------------------------	---------------



Close-up of sealed container



Close-up of seal

< REPORT >

Note: During the container loading supervision, TSInspection inspector randomly selected, opened and conducted visual identity check on shipping cartons only. Consequently, TSInspection makes no guarantee and/or warranty whatsoever as to the quantity and/or quality of the container contents. This Inspection Result relates exclusively to the work ordered and the lot inspected. This Inspection Report shall not be reproduced (except in full) without the approval of TSInspection and the Client. The inspection report reflects our findings at that time and place of inspection. Inspection is performed to the best of our ability and skills but without responsibility on our part, nor does it evidence shipment. This report does not relieve the seller/manufacturer of their contractual liabilities or prejudice from buyer's right for compensation for any apparent and/or hidden defects not detected during our inspection or occurring thereafter.

Inspector:	Simon Zhao	Date:	May 27, 2011
------------	------------	-------	--------------

**End of Inspection Report**